



## Multiroom Compatibility Firmware Update Release Notes

### **Mu-so & Mu-so Qb (v. 1.6)**

New: Multiroom compatibility with Uniti Atom, Uniti Star and Uniti Nova

New: Updated to latest Spotify library

New: Soft mute the audio when streams stop; this removes sharp transition when music stops

### **Classic Uniti Range, Network Players and Streaming Preamplifiers (v. 4.6)**

New: Multiroom compatibility with Uniti Atom, Uniti Star and Uniti Nova

New: Updated to latest Spotify library

New: Soft mute the audio when streams stop; this removes sharp transition when music stops

Fixed: DAB metadata encoding issue. Some accented characters were shown incorrectly

Fixed: Improved TIDAL stability

### **New Uniti Range (v. 2.6)**

New: Front panel multiroom control interface. Add and remove rooms from multiroom session

New: Front panel UI CD ripping error reporting and more feedback when ripping fails (Uniti Star only)

New: Added support for Naim app to report ripping status and errors in album view (Uniti Star only)

New: Now running latest Roon library

New: Now running latest Spotify library for improved responsiveness

New: Multiroom limit increased to 192kHz from 96kHz

Improved: Reduced CPU load when changing volume during multiroom session

Fixed: Album image will sometimes get stuck on-screen, or will fail to show image when track changes

Fixed: Some incorrect strings in Uniti Star ripping monitor

Fixed: When streaming via Airplay from certain iOS apps, unit would enter standby after the pre configured period

Fixed: When streaming from Mixcloud app via Chromecast, unit would enter standby after the pre configured period

Fixed: Input trim control on internal inputs

Fixed: Webpage network setup - sometimes shows incorrect list of available networks.

Fixed: ALAC 352.8 and 384kHz could have dropouts during playback

Fixed: Seek to time could occasionally skip track

Fixed: System system wide slowdown when there is no internet connection (caused by vTuner failed login)

Fixed: Unit would occasionally go into standby during setup wizard

Fixed: Unit could fail to go into standby after using Bluetooth

Fixed: Bluetooth could fail to multiroom correctly

Fixed: Multiroom compatibility issues with existing products,

Fixed: Wifi latency issues that could result in slow user experience from control apps

Fixed: Roon sometimes fails to play after sample rate change

Fixed: TIDAL would sometimes fail to play if username or password contained special characters

Fixed: TIDAL now playing metadata sometimes doesn't match app

Fixed: TIDAL token to ensure correct content variant is selected from TIDAL servers

Fixed: Occasional failure to generate audio signature when scanning music collections

Fixed: Remote control clock button now hides the clock

Fixed: Factory reset more robust

Fixed: Favourites not marked as unavailable if associated store is offline

Fixed: Ensure rips album folder names are legal (i.e. don't start with dot)

Fixed: Front Panel - UI can hang when cancelling rip from CD menu

Fixed: Front Panel - Proximity event hides ripping result

Fixed: Front Panel - UI sometimes slow to load

Fixed: Front Panel - Some menu items would time out too quickly back to the home screen

Fixed: Front Panel - Minor bugs with front UI during firmware update

Fixed: Front Panel - Minor bugs on multiroom now playing screens

Fixed: Front Panel - volume indicator sometimes stuck at zero after power on

Fixed: Front Panel - Fixed no metadata on some multiroom sources

---

This update also brings fundamental usability improvements and bug fixes for the Naim app; see all detailed improvements below.

### **Naim App - iOS v5.9.1**


- v5.9.1 includes support for improved multiroom compatibility across the product range.
- Introduces numerous improvements to the multiroom picker interface to support the products and improve usability
- Improves the robustness of joining a multiroom group
- Improves the experience of the Mu-so and Mu-so Qb firmware update process.
- Fixes an issue where the digital input sample rate was not displayed on the Now Playing screen
- Fixes an issue where 'No Track Playing' might have been presented during playback using TIDAL
- Fixes an issue where TIDAL playback may fail after an update
- Fixes an issue where the app might crash when viewing albums by location
- Fixes an issue where max volume and balance may be missing from input settings
- Fixes an issue where the date may be incorrectly displayed for a firmware update
- Fixes an issue where favourites from a Core in standby mode may not be displayed

## Naim App - Android v2.6


v2.6 includes support for improved multiroom compatibility across the product range

- Introduces numerous improvements to the multiroom picker interface to support the products and improve usability
- Improves the robustness of joining a multiroom group
- Improves the experience of the Mu-so and Mu-so Qb firmware update process
- Introduces the use of album artwork in situations where there is no artist artwork available
- Fixes an issue where CD input was incorrectly available to be disabled
- Fixes an issue where NAS shares were not selectable when configuring a backup
- Fixes an issue where shuffle and repeat may be displayed on inputs that don't support them
- Fixes an issue where max volume and balance may be missing from input settings
- Fixes an issue where the date may be incorrectly displayed for a firmware update

### Prior to Update



### With Update



Full lists of products affected by this new update are as follows:

- Mu-so
- Mu-so Qb
- Uniti Nova
- Uniti Star
- Uniti Atom

**Must be a 24-bit/192kHz variant:**

- NDS
- NDX
- ND5 XS
- SuperUniti
- NaimUniti
- NaimUniti 2
- UnitiLite
- UnitiQute
- UnitiQute 2
- NAC-N 172 XS
- NAC-N 272

**Important: In order for the unit to carry out the update it MUST be 24bit/192kHz capable.**

To identify if the unit is 24bit/192kHz capable, follow these instructions:

1. Press the 'Settings' button on the remote control
2. Scroll and select 'Factory Settings'
3. Scroll and select 'System Status'
4. Scroll to 'BC SW'. If the code starts with '3Dxxxx' you have the latest hardware and the update can be made. If it displays anything else then the update cannot be made.

If you have any questions regarding the update or are experiencing any issues installing the new firmware please contact the Technical Support Team.

T. +44 (0)1722 426 600

E. [support@naimaudio.com](mailto:support@naimaudio.com)